

SECTION 5. FIRE-FIGHTING MEASURES

SUITABLE EXTINGUISHING MEDIA:

WATER SPRAY

ALCOHOL-RESISTANT FOAM

DRY CHEMICAL

CARBON DIOXIDE (CO₂)

UNSUITABLE EXTINGUISHING MEDIA: HIGH VOLUME WATER JET

SPECIFIC HAZARDS DURING FIRE FIGHTING:

DO NOT USE A SOLID WATER STREAM AS IT MAY SCATTER AND SPREAD FIRE.

FLASH BACK POSSIBLE OVER CONSIDERABLE DISTANCE.

VAPORS MAY FORM EXPLOSIVE MIXTURES WITH AIR.

EXPOSURE TO COMBUSTION PRODUCTS MAY BE A HAZARD TO HEALTH.

HAZARDOUS COMBUSTION PRODUCTS:

CARBON OXIDES

SILICON OXIDES

FORMALDEHYDE

SPECIFIC EXTINGUISHING METHODS:

USE EXTINGUISHING MEASURES THAT ARE APPROPRIATE TO LOCAL CIRCUMSTANCES

AND THE SURROUNDING ENVIRONMENT.

USE WATER SPRAY TO COOL UNOPENED CONTAINERS.

REMOVE UNDAMAGED CONTAINERS FROM FIRE AREA IF IT IS SAFE TO DO SO.

EVACUATE AREA.

SPECIAL PROTECTIVE EQUIPMENT FOR FIRE-FIGHTERS:

WEAR SELF-

CONTAINED BREATHING APPARATUS FOR FIREFIGHTING IF NECESSARY.

USE PERSONAL PROTECTIVE EQUIPMENT.